



Intel® USB 3.0 eXtensible Host Controller Driver

Release Notes (3.0.4.65)

February 2014

Revision 1.4

Intel Confidential



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: <http://www.intel.com/design/literature.htm%20>

All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice.

This document contains information on products in the design phase of development. Do not finalize a design with this information. Revised information will be published when the product is available. Verify with your local sales office that you have the latest datasheet before finalizing a design.

Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See www.intel.com/products/processor_number for details.

Code names featured are used internally within Intel to identify products that are in development and not yet publicly announced for release. Customers, licensees and other third parties are not authorized by Intel to use code names in advertising, promotion or marketing of any product or services and any such use of Intel's internal code names is at the sole risk of the user.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2015, Intel Corporation. All rights reserved.



Contents

1	Introduction	5
	1.1 Scope of Document	5
	1.2 System Requirements	5
	1.3 Acronyms and Terminology	6
2	Release Kit Summary	8
	2.1 Release Kit Details	8
	2.2 Kit Contents	8
3	Important Notes	9
	3.1 USB 3.0 Collaterals	9
	3.2 Platform Best Known Configuration	9
	3.3 New Root Certificate Signing	9
4	Closed Issues	10
5	Known Issues	14



Revision History

Revision Number	Description	Revision Date
0.7	Initial Release.	September 2013
0.8	Alpha Release	October 2013
0.85	Alpha2 Release	December 2013
0.86	Beta Release	March 2014
0.90	ENG 3.0.0.27 Release	May 2014
0.95	ENG 3.0.0.31 Release	May 2014
1.0	PC/PV Release – 3.0.0.34	June 2014
1.1	HF1 Release - 3.0.1.41	August 2014
1.2	MR2 Release - 3.0.2.54	November 2014
1.3	MR3 Release - 3.0.3.60	December 2014
1.4	MR4 Release - 3.0.4.65	February 2015

§



1 Introduction

1.1 Scope of Document

This document provides release information about the Intel® USB 3.0 eXtensible Host Controller Driver. It covers Release Kit summary, Important Notes, Resolved Issues and Known Issues. This document is intended for OEMs and ODMs that are validating the Intel® USB 3.0 eXtensible Host Controller Driver on their platform.

1.2 System Requirements

The Intel® USB 3.0 eXtensible Host Controller Driver contains support for the following Intel Chipsets:

- Intel® 8 Series/C220 Chipset Family
- 4th Generation Intel® Core™ Processors
- Intel® C610 series Chipset Family
- Intel® 9 Series Chipset Family
- Intel® Pentium® Processor or Intel® Celeron® Processor N- & J- Series
- 5th Generation Intel® Core™ Processors
- Intel® Core™ M Processor

The following Operating Systems are supported:

Intel® 8 Series Chipset Family

4th Generation Intel® Core™ Processors

Intel® 9 Series Chipset Family

Intel® Pentium® Processor or Intel® Celeron® Processor N- & J- Series

5th Generation Intel® Core™ Processors

Intel® Core™ M Processor:

- Windows* 7 Operating System (both 32-bit and 64-bit versions).

Intel® C220 series chipset family

Intel® C610 series Chipset Family:

- Windows* 7 Operating System (both 32-bit and 64-bit versions).
- Windows* Server 2008 R2 Operating System.
- Windows* Small Business Server 2008 Operating System.

Note: The Intel® USB 3.0 eXtensible Host Controller Driver is not supported on Windows* XP and Windows Vista*. For these operating systems, ensure your BIOS settings have the




xHCI Mode set to "Auto" or "Smart Auto". This will reconfigure the USB 3.0 ports to function as USB 2.0 ports using the native Windows* EHCI driver. For more information, see the Wildcat Point-LP Platform Controller Hub (PCH) BIOS Specification document.

The Intel® USB 3.0 eXtensible Host Controller Driver Installer and Intel® USB 3.0 Monitor support the following languages:

- Arabic (International)
- Chinese (Simplified)
- Chinese (Traditional)
- Czech
- Danish
- German
- Greek
- English (United States)
- Spanish
- Finnish
- French (International)
- Hebrew
- Hungarian
- Italian
- Japanese
- Korean
- Dutch
- Norwegian
- Polish
- Portuguese (Brazil)
- Portuguese (Portugal)
- Russian
- Slovak
- Slovenian
- Swedish
- Thai
- Turkish

1.3 Acronyms and Terminology

Term	Description
BSOD	Blue Screen of Death (Stop Error)
CRB	Customer Reference Board
EHCI	Enhanced Host Controller Interface



Term	Description
FS	Full-Speed
HID	Human Interface Device (ex: keyboard or mouse)
HS	High-Speed
IBP	Intel Business Portal (https://businessportal.intel.com)
LS	Low-Speed
PCH	Platform Control Hub
RMH	Rate Matching Hub
SS	Super-Speed
USB	Universal Serial Bus
xHCI	eXtensible Host Controller Interface
WPP	Windows* software trace Pre-Processor



2 Release Kit Summary

2.1 Release Kit Details

Kit Name: Intel(R) USB 3.0 eXtensible Host Controller Driver

Version: 3.0.4.65

2.2 Kit Contents

The contents of this release kit include:

- Intel® USB 3.0 eXtensible Host Controller Driver Installer

The Intel® USB 3.0 eXtensible Host Controller Driver Installer "Setup.exe" will install the following drivers and application on the system:

- Intel® USB 3.0 eXtensible Host Controller Driver
- Intel® USB 3.0 Root Hub Driver
- Intel® USB 3.0 Host Controller Switch Driver
- Intel® USB 3.0 Monitor
- Intel® USB 3.0 eXtensible Host Controller Driver – Release Notes
- Intel® USB 3.0 eXtensible Host Controller Driver – Bring Up Guide
- Intel Software License Agreement

Note: It's recommended that USB3.0 driver should only be installed using the setup.exe. Proper device functionality cannot be ensured if INF installation is used.

§



3 *Important Notes*

3.1 USB 3.0 Collaterals

Please see the document "Intel(R) USB 3.0 eXtensible Host Controller Driver - Bring Up Guide" for information on driver installation and usage. This document can be found in the Intel® USB 3.0 eXtensible Host Controller Driver release kit.

Another useful document to reference is the "Intel(R) USB 3.0 eXtensible Host Controller Driver - Customer Validation and Debug Guide". This document is available on CDI. Please contact your Intel FAE for access.

3.2 Platform Best Known Configuration

Please refer to "Client Base Platform Best Known Configuration" from Intel Business Portal (IBP) for platform configuration setup that aligns to this milestone releases.

3.3 New Root Certificate Signing

The current driver is signed with 2048 Bit Root certificate. Some Windows* 7 OS image might not contain the correct root certificate to authenticate it. If this is the case, it's required to install Microsoft* KB [931125](#).

For more detail of 2048 Bit root certificate, see Root Certification Guidance - customer communication #549032.

§



4 Closed Issues

Issue #	Description	Resolution
4636660	When multiple USB2.0 HUBs (connected together with USB devices plugged in behind the HUBs) is unplugged from the Root Hub Port, under certain conditions a delay may be seen for the USB devices to be removed from the device manager.	Resolved in Release Rev: 3.0.4.65 (MR4)
4636977	An unknown publisher is displayed when launching the setup.exe installer	Resolved in Release Rev: 3.0.4.65 (MR4) (installer build 1.5.24.0)
4636270	A specific USB2.0 thumb drive may disappear from device manager if a file transfer is initiated after formatting the device.	Resolved in Release Rev: 3.0.3.60 (MR3)
4636313	A Bluetooth device may fails to connect to Bluetooth controller if the Bluetooth controller is turn off and on.	Resolved in Release Rev: 3.0.3.60 (MR3)
4636626	BSOD 0x9F may occurs on Windows 32bit during reboot stress test if specific Bluetooth\WiFi combo device is connected.	Resolved in Release Rev: 3.0.3.60 (MR3)
4802626	Lager file transfer over Bluetooth device may fails to complete.	Resolved in Release Rev: 3.0.3.60 (MR3)
4636726	If Bluetooth device is disabled through the taskbar icon, it may take 10 seconds for Bluetooth device to get disabled.	Resolved in Release Rev: 3.0.3.60 (MR3)
4994858	USB2.0 mouse may freezes in Windows login screen after resuming from S3 if an USB2.0 keyboard is connected to other USB port.	Resolved in Release Rev: 3.0.3.60 (MR3)
4636579	Frame counter may get reset after Isochronous USB device is plugged/unplugged from the system.	Resolved in Release Rev: 3.0.3.60 (MR3)
4636516	BSOD 0x50 caused by iusb3hub.sys may occurs during stress Sx/Reboot cycle.	Resolved in Release Rev: 3.0.2.54 (MR2)
4636373	Specific Bluetooth device may take long time to get disabled or enabled.	Resolved in Release Rev: 3.0.2.54 (MR2)
4636006	Under certain condition, specific High resolution USB3.0 ISOCH camera may fail to enumerate when connected to xHCI controller.	Resolved in Release Rev: 3.0.2.54 (MR2)
4636460	Specific Bluetooth device power state data is stuck in D0 when is connected to the xHCI controller if driver 3.0.1.41 is reinstalled	Resolved in Release Rev: 3.0.2.54 (MR2)
4636065	BSOD 0x7E caused by iusb3hub.sys may occurs during stress power cycle test.	Resolved in Release Rev: 3.0.2.54 (MR2)
3881963	On a specific USB3.0 Hub, the xHCI driver may send High Speed packets to Low/Full Speed device connected behind USB3.0 Hub after resuming from S4.	Resolved in Release Rev: 3.0.2.54 (MR2)



Issue #	Description	Resolution
2164715	Improved w/a for issue #4635699	Resolved in Release Rev: 3.0.2.54 (MR2)
5228776	Full Speed barcode scanner may fail to enumerate when connected behind a USB2.0	Resolved in Release Rev: 3.0.1.41
4043547	USB3.0 Pendrive may fail to enumerate when connected behind USB3.0 Hub after S4 power cycle	Resolved in Release Rev: 3.0.1.41
4636027	BSOD 0x9F may occurs during long S3 streets test	Resolved in Release Rev: 3.0.1.41
4802601	Certain Bluetooth device Power state data is stuck in D0 when is connected to the xHCI controller	Resolved in Release Rev: 3.0.1.41
4635699	In certain condition when a USB3.0 Hub is connected behind xHCI controller and both Hub and xHCI controller have entered selective suspend, the xHCI will fail to detect USB3.0 devices if plugged behind the USB3.0 Hub.	Resolved in Release Rev: 3.0.1.41
4635532	USB3.0 monitor application may crash under Windows 7 OS Simplified Chinese if USB3.0 device with a long name is connected to USB2.0 port.	Resolved in Release Rev: 3.0.1.41
4635987	Intel logo displayed in the installer windows is overlapped if display configuration is set to medium -125% under control panel	Resolved in Release Rev: 3.0.1.41 (installer build 1.5.16.0)
N/A	Added support for 5 th Generation Intel® Core™ Processors / Intel® Core™ M Processor	Resolved in Release Rev: 3.0.0.34
N/A	Added functionality (for the BayTrail M/D Platform only) to automatically reboot the platform after the driver is uninstalled through the control panel.	Resolved in Release Rev: 3.0.0.33 (installer build 1.5.9.0)
5317181	USB link doesn't transition to L2 when Bluetooth module is connected to the xHCI controller and LPM L1 support is enabled in the device.	Resolved in Release Rev: 3.0.0.33
4635482	Added support for BIOS ACPI definition for embedded hub ports.	Resolved in Release Rev: 3.0.0.31
4635372	BSOD 0x9F may occurs during reboot stress test if device descriptor information is corrupted.	Resolved in Release Rev: 3.0.0.31
4635687	xHCI driver may cause delay on Velocity Test Suit – suspend test.	Resolved in Release Rev: 3.0.0.31
N/A	Added support for WinPE 3.x environment.	Resolved in Release Rev: 3.0.0.31
4635443	xHCI driver incorrectly read the DeviceRemovable field from USB HUB descriptor causing internal device defined as non-removable to show up as removable device.	Resolved in Release Rev: 3.0.0.27



Issue #	Description	Resolution
4635480	BSOD 0x7E may occurs during platform stress test.	Resolved in Release Rev: 3.0.0.27
4635356	USB3.0 monitor application may crash when it's forced shutdown.	Resolved in Release Rev: 3.0.0.27
4635513	BSOD 0x9F may occurs during S4 stress test.	Resolved in Release Rev: 3.0.0.27
1024655	Added a new switch option (-s0) to allow a return code '0' instead of '14' when silent installation is used.	Resolved in Release Rev: 3.0.0.27 (installer build 1.5.6.0)
298094	BSOD 0x9F may occurs while platform goes to S3/S4 during stress test with dynamic delay enabled between s-states.	Resolved in Release Rev: 3.0.0.27
4802224	USB 3.0 synthetic HID device will not enter U1/U2 if the S3 wake is triggered by the device.	Resolved in Release Rev: 3.0.0.27
4802297	Improved xHCI driver handling of LPM L1 feature on device that only supports pre-errata version of LPM specification.	Resolved in Release Rev: 3.0.0.27
N/A	Added support for BayTrail M/D Platform.	Resolved in Release Rev: 3.0.0.19
N/A	Added support for Intel® 9 Series Chipset Family.	Resolved in Release Rev: 3.0.0.16
4635104	BSOD 0x9F may occurs during reboot test with WLAN/BT device connected to xHCI controller.	Resolved in Release Rev: 3.0.0.12
2164688	BSOD 0x9F may occurs during system Sleep & PnP on Win7 with WLAN/BT device connected to xHCI controller.	Resolved in Release Rev: 3.0.0.12
3709786	Improve BSOD 0xE8086002 check in the release driver.	Resolved in Release Rev: 3.0.0.12
2164685	Bluetooth module (WiFi/BT combo) connected to the xHCI controller may show up with yellow bang after resuming from S4 stress test cycle.	Resolved in Release Rev: 3.0.0.12
3709829	BSOD 0xE6 may occurs during S3 stress testing with driver verifier enabled and Bluetooth module (WiFi/BT combo) connected to the xHCI controller.	Resolved in Release Rev: 3.0.0.12
3709981	BSOD 0x9F may occurs during warm reboot stress testing with Bluetooth module (WiFi/BT combo) connected to the xHCI controller.	Resolved in Release Rev: 3.0.0.12
4802017	After an overcurrent event, USB3.0 device connected behind USB3.0 HUB will fail to enumerate if the USB3.0 device re-connected again on the same port.	Resolved in Release Rev: 3.0.0.12
3709824	BSOD 0xD1 may occurs during burn-in test.	Resolved in Release Rev: 3.0.0.8

Closed Issues



Issue #	Description	Resolution
3709917	Updated driver w/a for issue 3707101 - USB3.0 monitor fails (video hang) when connected to USB3.0 port.	Resolved in Release Rev: 3.0.0.8
4043513	System will auto wake from Sx state if USB keyboard is reconnected while system is in the Sx state.	Resolved in Release Rev: 3.0.0.8
3709806	Self-powered USB3.0 HDD may not enumerate correctly if the HDD is reconnected to a different USB port when the system is in S4.	Resolved in Release Rev: 3.0.0.8

§



5 Known Issues

Issue #	Description
N/A	

§