

BTW12.0.1.670 USB Driver Package



BTW12.0.1.670 USB Driver Package

Release Notes

June 30, 2015

Confidential and Proprietary Information

© Broadcom Corp., 2008, All rights reserved.
Printed in United States of America.
16340 West Bernardo Drive
San Diego, CA 92127
Phone: (858) 385-8800
Fax: (858) 385-8810

BTW12.0.1.670 USB Driver Package

LICENSED SOFTWARE

©200x Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

BTW12.0.1.670 USB Driver Package

INTRODUCTION

This software package consists of the BTW12 build 12.0.1.660 that contains the software applications and drivers that can be installed on Win8.1 and WinNext Intel x86 / x64 USB platforms

This release of BTW12 contains drivers for the x86 / x64 USB platforms that passed WHCK tests.

CUSTOMER SUPPORT PORTAL (CSP)

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

BTW12.0.1.670 USB Driver Package

Issues Fixed – Windows 8

Defect ID	Description
BLTH03469407	change 43241 FW request for upgrade FW baseline from 249 to 311[670]
BLTH03469836	Upgrade VID_04CA&PID_2012, VID_0489&PID_E096 FW baseline of BCM43142A0 from 277 to 311 - Win8.1/Win10 WHCK/HLK[670]
BLTH03469970	DW1704 43142A0 FW update - 32bit & 64bit - win8/win8.1/win10 WHCK DUA[670]
BLTH03469530	43142A0 FW update - 32bit & 64bit - win8/win8.1/win10 WHCK DUA[670]
BLTH03469516	4350C5 FW update - 32bit & 64bit - win8/win8.1/win10 WHCK[670]
BLTH03470099	Combined USB/UART MSI driver installer works only for DEV+WHCK package, fails on WHCK-only. [660]
BLTH03467951	Mouse Cursor of Controlling System Is Visible When using Remote Keyboard and Mouse. [660]
BLTH03470070	Updated MUP xml for Win10[660]
BLTH03469305	Remove devices from BTW12 USB -Dev package[650]
BLTH03469166	Upgrade HP FW baseline of BCM43142A0 from 249 to 311 - Win8.1/Win10 WHCK/HLK[650]
BLTH03468506	Remove devices from Win10 Section in bcbtums-DEV file[640]
BLTH03468502	Check in INF and DUA signed files[640]
BLTH03467863	Devices listed in the -DEV driver package (USB and UART) before12.0.1.610 will not install on Win10[630]
BLTH03467860	update USB driver based on latest Logo'd devices, add Logo signed files for 12.0.1.616 submission[630]
BLTH03467866	Produce MSI driver installer for DEV files[630]
BLTH03467416	Add Logo signed USB driver version 12.0.1.610[620]
BLTH03466532	4350C5 FW update - 32bit & 64bit - win8/win8.1 WHCK[610]
BLTH03466889	Add new project in Win8 -dev package for 20703A1 Runtime RAM Dongle[610]
BLTH03467190	Add 20702 standalone devices for Win10 DUA[610]
BLTH03467195	Devices with Win8.1 logo but not Win10 Logo will not install on Win10[610]
BLTH03461154	Use VS 2012 for phone library and sample apps[610]
BLTH03466221	4350C5 6414 device to DEV package with test generic 0080.0000 FW [600]
BLTH03463520	Update FW and add new project in Win8 -dev package for 4350C5/43602/4371C2[600]
BLTH03464015	Need new VID/PID 04F2/B4A2 to be added in BTW12 for BCM4356A2 - Win8/8.1 WHCK[600]
BLTH03465837	Need new VID_13D3&PID_3492 and VID_13D3&PID_3485 to be added and change FW in BTW12 for BCM4356A2 with WHCK build[600]
BLTH03461219	Moved 4350zae module ID 0A5C/6414 from DEV to WHCK driver package-Win8 [590]
BLTH03462478	BTW 12 USB: 4350C5 FW update - 32bit & 64bit - win8/win8.1 WHCK[590]
BLTH03462262	Fix install issue[590]
BLTH03463221	BTW file transfer authorization dialog[590]
BLTH03463959	Music stops streaming while OPP or FTP file transfer is initiated. [590]
BLTH03461468	Use Obex over RFCOMM when audio is connected[1570]
BLTH03461429	File transfer fails (Lenovo 43162) [1570]
BLTH03459311	pop up message twice when transfer file in win10[1560]
BLTH03460241	Fix UI language for uninstall[1560]
BLTH03458603	Added new vid/pid in BTW12 for BCM4356A2 - Win8/8.1 WHCK (x86/x64) [1550]
BLTH03459109	New VID/PID 04F2/B4A1 added in BTW12 for BCM43142A0 - Win8/8.1 WHCK[1550]
BLTH03456492	Use locale language for install[1540]
BLTH03458513	BTW Phone App A2DP problems[1520]
BLTH03457831	Add A2DP connect/disconnect to BtwPhoneLib[1510]
BLTH03456770	Driver update for .310 btwavdt[1450]

BTW12.0.1.670 USB Driver Package

BLTH03456415	Unable to install on Win10[1400]
BLTH03454957	BTW12 Localization of toast messages for Win10[1400]
BLTH03456396	BTW RssiLib suppor for BW not installed[1400]
BLTH03408640	Unable to connect "Play audio stored on other computer through my computer"(AV sink) [1300]
BLTH03452630	Memory leak in btwavdt.sys when performing A2DP Sink[1300]
BLTH03453116	BSOD issue by btwaudio.sys when cold boot stress testing[1300]
BLTH03449608	Add DRM signature attributes to btwaudio INF file[1300]
BLTH03448807	Both sink and source is connected after reboot[1300]
BLTH03448679	BTW proximity API and sample app or native code win8[1300]
BLTH03444465	No sound output after power off/on BT headset [1300]
BLTH03447344	Change 4356A2 FW for WHCK- 640E - 32/64 bit - win8/win8.1 - WHCK[1280]
BLTH03448854	add new 4349 device VID/PID = 0A5C/6404 - 32/64bit - win8/8.1 - DEV[1280]
BLTH03449866	Please add 43602 (20703A1) Project VID/PID to BTW 12 32/64 bit as non-WHCK[1280]
BLTH03446560	Change FW for 4356A2 w/ radio control added - 640E - 32/64 bit - win8/win8.1 - DUA[1280]
BLTH03444465	No sound output after power off/on BT headset.[1275]
BLTH03448679	Added native code support to the RSSI API and native code sample (in C++). Added support for 64-bit build.[1275]
BLTH03445232	Upgrade FW baseline of VID/PID 105B/E065 of BTW12 for BCM43142A0 - Win8/8.1 WHCK[1250]
BLTH03445885	Add new 4350C0 devices VID/PID = 0A5C/640F and 4339A1 0A5C/6403 - 32/64bit - win8/8.1 - DEV[1240]
BLTH03438592	LCFC Factory request for enable/disable Bluetooth discovery[1220]
BLTH03444564	Change FW for 4350C0 w/ radio control fix - 0A5C/640D - 32bit & 64bit - win8/win8.1 DEV[1210]
BLTH03444555	Change FW for 4356A2 w/ radio control added - 640E - 32/64 bit - win8/win8.1 - DUA[1210]
BLTH03444492	BTW12 USB Add CM3 Workaround flag for 0489/E096 and 185F/2167 devices 32/64 WHCK[1210]
BLTH03442669	Need new VID/PID 13D3/3482 and 13D3/3484 to be added in BTW12 for BCM43142A0 - Win8/8.1 WHCK (both x86 and x64) [1210]
BLTH03441057	VID/PID 0A5C/745E of BTW12 for 20703A1- Win8/8.1 WHCK[1210]
BLTH03444469	Need new VID/PID 04F2/B49D to be added in BTW12 for BCM43142A0 - Win8/8.1 WHCK (both x86 and x64) [1210]
BLTH03440768	VID/PID to be added in BTW12 bcbtums driver 4356 NGFF combo module[1200]
BLTH03441863	BTW RSSI api does not work for LE devices[1190]
BLTH03441626	BTW get raw rssi function needs to be moved to service[1170]
BLTH03440279	Added proximity sample app[1170]
BLTH03440032	new project 4350zae - VID/PID=0A5C/640D - 32bit & 64bit - win8/win8.1 DEV[1170]
BLTH03434920	Added 43228 + 20702 M.2 project, WHCK package [1160]
BLTH03436589	VID/PID to be added in BTW12 bcbtums WHCK driver for 43162 NGFF combo module[1160]
BLTH03435444	Changed FW for 4360+20702 HMB - VID/PID = 0B05/180A - WHCK[1160]
BLTH03439141	Drivers updated for BTW12 btwaudio, btwavdt and btwrchid. [1150]
BLTH03238641	Software Off/On fails to work as expected on source side while streaming music. . [1150]
BLTH03423568	Change FW of VID/PID 105B/E065 of BTW12 for BCM43142A0 - Win8/8.1 WHCK. [9990]
BLTH03410336	No sound output after power off/on BT speaker[9990]
BLTH03422265	VID/PID 0489/E096 added in BTW12 for BCM43142A0 - Win8/8.1 WHCK[9980]
BLTH03410383	BTW12 USB device VID_0A5C&PID_745E from dev inf to whck inf[9980]
BLTH03144313	Support multi party calls for Nokia HFP[9980]
BLTH03410369	USB change name of 20703 device to "4.1" instead of "4.0" bcbtums-DEV[9970]

BTW12.0.1.670 USB Driver Package

BLTH03338372	Unable to download phonebook 2nd time after a delay of 3min[9950]
BLTH03301432	Update 43142 projects in Win8/8.1 to baseline 249[9890]
BLTH03255349	Change FW for 20702 projects -DUA[9880]
BLTH03303441	driver update for btwserialbus and bcbtums files[9880]
BLTH03273509	PSExec cannot upgrade BTW[9860]
BLTH03236907	Signed files for Win8 and 8.1[9850]
BLTH03219394	Change 20702A1 FW to baseline v1483 - fix audio playback *glitch* when inquiry[build 9840]
BLTH03219340	Update 20702A1 baseline to 1483[build 9840]
BLTH03193437	Add new VID_0B05/PID_180A with 20702 FW to BTW WHCK[build 9840]
BLTH03208191	Add new Projects to BTW 12 32/64 bit non-WHCK[build 9840]
BLTH03146284	Request a win8 WHCK BT driver[build 9820]
BLTH03122463	Driver only installer can't re-install the driver once removed from device manager[build 9810]
BLTH03100096	BCM43162 VID_0489&PID_E079 change FW to 0066.0115 -Win8/8.1 WHCK[build 9800]
BLTH03098021	Add 4352+20702 M.2 project to -BTW - VID/PID = 0A5C/216F, for WHCK[build 9760]
BLTH03084903	Add 4352+20702 M.2 project to -BTW - VID/PID = 0A5C/216F[build 9760]
BLTH02611628	Reject From HF fails[build 9750]
BLTH03045672	Added support for requested device in -DEV USB driver package[build 9665]
BLTH03053340	Customization for HF, PBAP, MAP[build 9665]
BLTH02292915	Wi-Fi Display App update[build 9600]
BLTH03041234	VID/PID to be added in BTW12 bcbtums driver for 43228 NGFF WHCK[build 9590]
BLTH02995019	Add BCM 43162Z FW to BTW12 WHCK .inf under Family WHCK[build 9580]
BLTH02938853	Change 20702A1 (PID/VID: 04CA/200F) FW TX power table [build 9580]
BLTH02940582	Spy doesn't work in USB driver-only deploys[build 9580]
BLTH02978139	Sleep/Hibernate-> Headset not connects to HF service[build 9550]
BLTH02958066	BT Headphone audio quality is poor when resuming from S4[build 9550]
BLTH02986899	driver update for btwaudio, btwavdt and btwrchid[build 9550]
BLTH02970668	Change FW for 43162 NGFF - VID/PID = 0489/E079 &0930/0229 - WHCK[build 9500]
BLTH02970670	drivers update for btwaudio, btwavdt and btwrchid[build 9400]
BLTH02970679	drivers update for bcbtums and btwserialbus[build 9400]
BLTH02970670	drivers update for btwaudio, btwavdt and btwrchid[build 9400]
BLTH02970679	drivers update for bcbtums and btwserialbus[build 9400]
BLTH02891337	Only HFP profile will be connected if pair certain BT Speaker to PC twice[build 9390]
BLTH02924854	Remove specific text from customer customized ini file for BTW install[build 9390]
BLTH02954435	BT device tray icon on task bar not sync with BT device[build 9390]
BLTH02596954	FTP file transfer fails during Inquiry[build 9390]
BLTH02919515	Audio/image/video file cannot be received by another user [build 9380]
BLTH02876384	File is overwritten without warning when same name file is received. [build 9380]
BLTH0292497	added in BTW12 bcbtums WHCK driver for 43162 NGFF combo module[build 9360]
BLTH02921339	Install remote control HID driver on demand[build 9350]
BLTH02887678	Spy should try BTWAMPFL after USB or UART transport drivers[build 9200]
BLTH02853765	HID device connection is going but mouse movement seen on both systems. [build 9200]
BLTH02893083	btwaudio driver whql signed files check in[build 9200]
BLTH02870615	PC-PC AV Connected, But Music is not heard on AV sink system[build 9190]
BLTH02790193	Around 1 Sec audio break is observed after 20-30 sec in BT HS[build 9180]
BLTH02850032	Added VID/PID (185F/2167) to be added in BTW12[build 9170]
BLTH02841366	Added VID/PID (04CA/200F) in BTW12[build 9170]

BTW12.0.1.670 USB Driver Package

BLTH02839533	Remove CM3 INF flag for 4335 based chips[build 9170]
BLTH02837679	Connect HID device opens full screen HIDdevice tray[build 9170]
BLTH02817451	HID Device connection is not going through. [build 9150]
BLTH02820538	VID/PID (13D3/3435) to be added in BTW12 for BCM20702A1_4352 [build 9140]
BLTH02776073	Change 43162 FW for VID/PID 0489/E079 - win8 & win 8.1 -DEV [build 9140]
BLTH02764302	Added VID/PID 0A5C/745D for 20703A0 Serial Flash Dongle non-UHE [build 9140]
BLTH02710117	VID/PID to be added in BTW12 bcbtums driver for 4352 NGFF [build 9140]
BLTH02820542	VID/PID (13D3/3456) added in BTW12 for BCM20702A1_4352 [build 9140]
BLTH02779743	Add ACPIID BCM2E5C to btwserialbus.inf file for 43241B4 Project [build 9140]
BLTH02818753	Change 43228+20702 FW for module VID/PID 04CA/200E WHCK [build 9140]
BLTH02818782	MSI based installer does not work on x64[build 9130]
BLTH02797953	Add localization support to new MSI driver installer[build 9120]
BLTH02711846	HFP API - Hold the active call then hang up,call does not end. [build 9110]
BLTH02507326	Mouse movement is not smooth during HID device connectionbuild 9110]
BLTH02713727	Force to end task via taskkill[build 9100]
BLTH02741538	BTTray handle count increase in Mem usage analysis [build 9090]
BLTH02711938	Add new project 43162 NGFF into BTW - VID/PID = 0A5C/216E[build 9060]
BLTH02708124	Add new project 43162 NGFF into BTW - VID/PID = 0930/0229[build 9060]
BLTH02707915	change 20702 FW to baseline 1443.0000 - LE Dual Mode fix - Win8/8.1 WHCK
BLTH02704802	Added in BTW12 bcbtums driver for 43162 NGFF combo module[build 9060]
BLTH02698089	43142A0 USB hub failure workaround[build 9060]
BLTH02698090	change 20702 FW to baseline 1443.0000 - LE Dual Mode fix - Win8/8.1 WHCK
BLTH02694665	driver update for bcbtums and btwserialbus [build 9000]
BLTH02631893	Merge btwrsupport code for LS and 4.0 radios[build 9000]
BLTH02616726	Add 4352z ngff combo device into BTW -VID/PID = 0A5C/216B [build 9000]
BLTH02603829	AddDW1708 43142Y combo device into BTW - VID/PID = 0A5C/216A [build 9000]
BLTH02577897	Radio on/off does not work on Win8.1 and BT 3.0 radio[build 9000]
BLTH02629831	Uninstall after OS upgrade[build 9000]
BLTH02677803	Add 43142Y ngff combo device into BTW -VID/PID = 0A5C/216D [build 9000]
BLTH02663314	change 43142 FW for device 2007 - Win8 and 8.1 WHCK package [build 9000]
BLTH02659745	Change 43228+2072 combo FW for module VID/PID 105B/E066 - WHCK[build 9000]
BLTH02657213	Need VID/PID to be added in BTW12 bcbtums driver for 43228 NGFF combo module [build 9000]
BLTH02643745	43142A0 FW for module VID/PID 105B/E065 - win8 & win 8.1 WHCK [build 9000]
BLTH02626279	Remote mouse not smooth when use "Remote Keyboard and Mouse"[build 8070]
BLTH02641822	BT P2P WHCK failure. [build 8060]
BLTH02570348	Sleep PnP test BSOD due to BTW. [build 8050]
BLTH02557968	HFP and A2DP services are not connected if the headset is removed and paired again. [build 8030]
BLTH02540444	BT headset can't auto connect after re-paired. [build 8030]
BLTH02528392	Please add BRCM Generic 43228Z project (0A5C/2169) to BTW12 Win8 and Win8.1. [build 8030]
BLTH02526254	Help files for Chinese language are incorrect. [build 7850]
BLTH02513564	WHCK test failes with BTW installed on Harrisbeach. This resulted in changes to the BT stack server and is therefore listed here. [build 7820]
BLTH02420557	Change 20702 FW to baseline 1315.0000. [build 7402]
BLTH02377257	Change the hex file to for 43142 combo module VID/PID = 105B/E065. [build 7200]

BTW12.0.1.670 USB Driver Package

BLTH02375657	Connection failed when connected with Sony wireless speaker SRS-BTV5. [build 7100]
BLTH02309586	Driver to fix Windows 8 to WinBlue upgrade. [build 7100]
BLTH02272762	Change FW hex file for 4352 NGFF into BTW - VID/PID = 0930/0223. [build 7100]
BLTH02265548	Update for help file. [build 7000]
BLTH02259154	Update Supra/Bumblebee/Vegas hex files to add LED Radio Off state. [build 7100]
BLTH02258953	Need VID/PID to be added in BTW12 bcbtums driver for 4352+20702 NGFF combo module. [build 7100]
BLTH02253676	Add new project 4352 NGFF into BTW - VID/PID = 0930/0223. [build 7100]
BLTH02194130	Device Install Check For Other Device Stability WHCK test fails for 4352 using 6273 driver. [build 7100]
BLTH02246956	Update HEX files to add LED Radio Off state. [build 6950]
BLTH02225042	Added new VID/PID 0A5C/2167 for 43142Y (NGFF) to BTW 12 (non WHCK) and update FW for existing Project. [build 6900]
BLTH02221771	Add new project 43142 combo device into BTW - VID/PID = 0A5C/21FE. [build 6900]
BLTH02219171	Changed 43142 FW due to output power changes - 04CA/2007. [build 6900]
BLTH02211080	Need VID/PID to be added in BTW12 bcbtums driver for 4360+20702 combo module. [build 6900]
BLTH02210954	BTItunesPlugin.exe error pop-out when reboot system with iTunes open. [build 6900]
BLTH02209065	Please update FW in BTW 12 for BRCM Generic 4335B0 VID/PID 0A5C/2166. [build 6900]
BLTH02208957	Need VID/PID to be added in BTW12 bcbtums driver for 43142 combo module. [build 6900]
BLTH02090526	Pop up an exclamation mark in the system tray. [build 6850]
BLTH02194154	Fix security vulnerabilities as per MSDN documentation. [build 6800]
BLTH02205419	WHCK signed bcbtums version 12.0.0.6273. [build 6600]
BLTH02179089	Unknow Bluetooth peripheral device will be added to Devmgmr after pairing with BT HS. [build 6600]
BLTH02178977	BTW 12 USB: change 43142 FW for LED changes- 04CA/2007. [build 6600]
BLTH02177046	Change the hex file to new release for 43228+20702 combo module VID/PID = 105B/E066. [build 6600]
BLTH02177043	Change the hex file to new release for 43142 combo module VID/PID = 105B/E065. [build 6600]
BLTH02175333	BT speaker still shows in playback after removed this device in Win8. [build 6600]
BLTH02163635	BT still able to inquiry when air-plane mode ON. [build 6600]
BLTH02162046	Add new program (4352z) and update existing FW program (4335B0). [build 6600]
BLTH02140296	Need support in BTW 12 for testing the new 4360 chip 0A5C_21FC. [build 6600]
BLTH02177310	Need VID/PID to be added in BTW12 bcbtums driver for 20702+4352 combo module. [build 6500]
BLTH02088868	Not able to search nearby devices after software off-on. [build 6500]
BLTH02143228	Add bcmhidnossr package to BTW install. [build 6400]
BLTH02137044	Display turns on by plugging in USB device when airplane mode is turned on. [build 6400]
BLTH02135217	Installation log is not generated with f2 option. [build 6350]
BLTH02107254	BTW 12 FTP Fails eventually after numerous attempts. [build 6300]
BLTH02105355	43142 Combo card does not enumerate correctly. [build 6300]
BLTH02092149	Incorrect File size shown if remote has a large file. [build 6200]
BLTH02081488	BTW FW Update for 4352 VID/PID 13D3/3404. [build 6100]
BLTH02046114	Change the 20702 family hex files to new release with HID fix (HID failed to disconnect after BT off) in baseline 1055.0000. [build 5900]

BTW12.0.1.670 USB Driver Package

BLTH02046091	Add new project 20702 + 4352 combo device into BTW - VID/PID = 0A5C/21FB. [build 5900]
BLTH02032248	Change the hex file to new release for 43142 combo module VID/PID = 105B/E065. [build 5900]
BLTH01995484	BT Stack COM server crash observed during FTP server system power cycle. [build 5900]
BLTH02056537	Stack server may crash when PAN connecting to iPhone. [build 5860]
BLTH02051939	Correct btwavdt driver event initialization problem. [build 5850]
BLTH02051763	Cannot establish PAN when paired with Smart phone. [build 5850]
BLTH02029896	Change btwdins service installation path. [build 5600]
BLTH01970656	BSOD on Win832/64bit OS: Pair & Connect BT headset and plug out dongle. [build 5300]
BLTH01886586	BSOD 0xC4 occur during Sleep and PNP with IO WHCK test. [build 5300]
BLTH01957652	Driver update for btwpanfl and btwampfl. [build 5200]
BLTH01883550	BTWPANFL BSOD. [build 5200]
BLTH01945282	OPP file transfer fails to switch to AMP when PAN-AMP file transfer is cancelled/PAN connection is disconnected. [build 5200]
BLTH01942109	Unable to reconnect PAN when PAN is disconnected during PAN +OPP data transfer. [build 5200]
BLTH01940738	OPP file transfer stops when PAN and OPP file transfer initiated immediately one after other. [build 5200]
BLTH01895970	Congestion issue of PAN over AMP feature. [build 5200]
BLTH01860770	Support for btwpanfl filter. [build 5200]
BLTH01852235	PAN Filter Driver Development. [build 5200]
BLTH01911723	BTHPAN BSOD in AMP over PAN testing. [build 5200]
BLTH01904072	PAN over AMP: File transfer from both directions causes one side timed out. [build 5200]
BLTH01904071	PAN over AMP: Occasionally PANFL to PANFL fails. [build 5200]
BLTH01835097	A2DP audio is not heard on remote device after starting the Obex transfer (L2CAP) to the same or different device. [build 5200]
BLTH01853690	Win8: mouse power status will disappear after s3, s4, s5 or restart. [build 5200]
BLTH01900582	Unrecognized word is displayed during BTW installation. [build 5100]
BLTH01897140	Add support for new combo device into BTW - VID/PID = 0930/0221. [build 5100]
BLTH01896005	Change the BTW12 single installer sequence. [build 5000]
BLTH01889952	System restarts automatically while BTW installation. [build 5000]
BLTH01855145	After fresh install and pairing and try AV connection PC-PC, no audio is heard in sink PC. [build 4900]
BLTH01811642	BTW not able to connect headset after Software Off-on multiple times. [build 4900]
BLTH01875628	Change the 20702 standalone family hex files to new release with HID fix (HID failed to disconnect after BT off) in baseline 1055.0000. This is for devices 21E6 and 021E. [build 4800]
BLTH01870402	Change the 20702 standalone family hex files to new release with HID fix (HID failed to disconnect after BT off) in baseline 1055.0000. This is for device E052. [build 4700]
BLTH01852199	Add new device into BTW - VID/PID =0489/E062. [build 4600]
BLTH01507005	Lync: Music does not switch to AV if remote user declines the call. [build 4500]
BLTH01800186	Change the 20702 standalone family hex files to new release with fix for LE HID reconnect failure in baseline 1010.0000. [build 4400]
BLTH01793826	Change friendly name for 0A5C/21F1 for Windows 8. [build 4400]
BLTH01811456	Fix for BTW toast notification under metro style. [build 4300]

BTW12.0.1.670 USB Driver Package

BLTH01809850	Change the 01A3 20702 device hex file to new release with fix for LE HID reconnect failure in baseline 1010.0000. [build 4200]
BLTH01795256	Switch to desktop from metro. [build 4200]
BLTH01762024	Cannot connect to headset after BT off/on using wireless switch. [build 4200]
BLTH01795264	Add E031 20702 A0 device into legacy driver package in BTW12. [build 4100]
BLTH01763966	Change the FW hex file to new release BTW for Broadcom 20702 module VID/PID = 0489/E042. [build 4050]
BLTH01751821	Send a 0 byte file from BRCM to Intel will get error message "The request could not be honored". [build 4000]
BLTH01724455	FTP file access permission is not show on the Start screen (CSP-557864) [build 4000]
BLTH01766058	There are two BT icon on system tray when airplane mode ON. [build 3800]
BLTH01753585	Control UI does not open after pairing with BLE Key fob and trying to open control UI of fob from devices and printers BT stackserver exits. [build 3550]
BLTH01747213	BT tray icon status has no change in airplane mode ON. [build 3500]
BLTH01739065	Stackserver and BTTray Disk I/O to be reduced per customer requirements. [build 3500]
BLTH01726012	Sync is not successful after resumed from hibernate. [build 3400]
BLTH01721130	Bluetooth COM server crash observed during AV connection after system resume from hibernate mode. [build 3400]
BLTH01735976	BTW is non-functional for devices not serviced by bcbtums.sys. [build 3200]
BLTH01727834	20702 serial flash module ON/OFF function doesn't work. [build 3100]
BLTH01727817	BtStackServer does not close FTP Client application correctly when system is put in S3/S4 state. [build 3100]
BLTH01576198	File transfer does not switch to AMP after system resumes from power cycles (Sleep/hinernate). [build 3100]
BLTH01726113	Driver update for btwampfl. [build 3000]
BLTH01726058	Reduce time to start-up stackserver. [build 3000]
BLTH01724288	BT Stackserver crashes while connecting to headset. [build 3000]
BLTH01703390	Stackserver and BTTray Disk I/O to be reduced per customer requirements. [build 2950]
BLTH01706314	BTW does not switch to AMP when FTP to Atheros stack. [build 2800]
BLTH01688847	Need VID/PID 0489/E047 to be enabled in BTW12 bcbtums driver for 4313+20702 combo module. [build 2800]
BLTH01688845	Need VID/PID 0489/E033 to be enabled in BTW12 bcbtums driver for 20702 flash module. [build 2800]

BTW12.0.1.670 USB Driver Package

Driver Signing Report – Windows 8.1 and Win10

Folder: BTW 12.0.1.670_***/Win8.1/Win32/

Driver:	Signed?	Signature:	Valid?	Submission ID:	Version:	OS list:
bcbtums-win8x86-brcm.cat	Yes	WHQL	Yes	1736913	12.0.1.653	Win8.1 Win10
--> btwampfl.sys					12.0.1.410	
--> btwrsupportservice.exe					12.0.0.8048	
--> bcmbtrsupport.dll					12.0.1.410	
--> btwdi.dll					12.0.0.7030	
--> bcbtums.sys					12.0.1.410	
btwaudio.cat	Yes	WHQL	Yes	1717586	12.0.1.330	Win8.1
--> btwaudio.sys					12.0.1.310	
--> btwavdt.sys					12.0.1.330	

Folder: BTW 12.0.1.670_***/Win8.1/Win64/

Driver:	Signed?	Signature:	Valid?	Submission ID:	Version:	OS list:
bcbtums-win8x64-brcm.cat	Yes	WHQL	Yes	1736913	12.0.1.653	Win8.1 Win10
--> btwampfl.sys					12.0.1.410	
--> btwrsupportservice.exe					12.0.0.8048	
--> bcmbtrsupport.dll					12.0.1.410	
--> btwdi.dll					12.0.0.7030	
--> bcbtums.sys					12.0.1.410	
btwaudio64.cat	Yes	WHQL	Yes	1717586	12.0.1.330	Win8.1
--> btwaudio.sys					12.0.1.310	
--> btwavdt.sys					12.0.1.330	