DOS Flash Utility SOP

1. Copy BIOS folder to USB storage.

2. Power on system.

3. When you see the LOGO or hear one short beep, please press "Delete" to enter BIOS Setup Utility.

4. Choose "Authentication" page and select "Secure Boot" to disabled.

5. BIOS Setup Utility will disable "Secure Boot"

6. Choose "Boot Options" page and select "Launch CSM" to Always.

7. Select "Boot Filter" to Legacy.

8. Choose "Exit" page and select "Save & Exit Setup" and press "Enter".

9. Select "Yes" to restart.

10. Press hot key F12 to enter Boot Menu, and select USB thumbdrive.

11. Enter "\Service\DOS" folder.

12. Execute "FLASH.bat" file.

13. Process to flash BIOS (don't reset).

14. After finish , Press the power button to shut down the system.

15. Boot system , When you see the LOGO or hear one short beep, please press "Delete" to enter BIOS Setup Menu.

16. Select "Load Default Settings" and press "Enter".

17. Select "Yes" to load default setting.

18. Select "Save & Exit Setup" and press "Enter".

19. Select "Yes" to restart.

PS. System may reboot 2 or 3 times after flash BIOS. This is normal behavior.