# Windows Flash Utility SOP

v1.2

1. **Please enter "WIN" folder and select "Flash.bat".**

2. **Please double click "Flash.bat".**

3. **The system will prompt a command window and select "Yes" to continue process.**

4. **Please wait BIOS update process. Please restart your system after updating BIOS completely.**

5. **When you see the LOGO or hear one short beep, please press "Delete" to enter BIOS Setup Menu.**

6. **Change page to "Exit".**

7. **Select "Load Default Setting" and press "Enter". Select "Yes" to load default settings.**

8. **Select "Save & Exit Setup" and press "Enter".**

9. **Select "Yes" to restart.**