



Windows Flash Utility SOP

V1.3

1. Please enter "WIN" folder and double click "Flash.bat".



2. Please wait BIOS update process. Please restart your system after updating BIOS completely.
3. When you see the LOGO or hear one short beep, please press "Delete" to enter BIOS Setup Menu.
4. Change page to "Exit".
5. Select "Load Default Settings" and press "Enter". Select "Yes" to load default setting.



6. Select "Save & Exit Setup" and press "Enter". Select "Yes" to restart.

