



Windows Flash Utility SOP

v1.4

1. Please enter “WIN” folder and select “FLASH.bat”.




2. Please double click ”FLASH.bat”.
3. The system will prompt a command window and select “Yes” to continue process.



4. Please wait BIOS update process. Please restart your system after updating BIOS completely.
5. When you see the LOGO or hear one short beep, please press “Delete” to enter BIOS Setup Menu.
6. Change page to “Exit”.

7. Select “Load Default Setting” and press “Enter”. Select “Yes” to load default settings.



8. Select “Save & Exit Setup” and press “Enter”.

9. Select “Yes” to restart.

