

DOS Flash Utility SOP

- 1. Copy BIOS folder to USB storage.**
- 2. Power on system.**
- 3. When you see the LOGO or hear one short beep, please press “Delete” to enter BIOS Setup Utility.**
- 4. Choose “Authentication” page and select “Secure Boot” to disabled.**
- 5. BIOS Setup Utility will disable “Secure Boot”**
- 6. Choose “Boot Options” page and select “Launch CSM” to Always.**
- 7. Select “Boot Filter” to Legacy.**
- 8. Choose “Exit” page and select “Save & Exit Setup” and press “Enter”.**
- 9. Select “Yes” to restart.**
- 10. Press hot key F12 to enter Boot Menu, and select USB thumbdrive.**
- 11. Enter “\Service\DOS” folder.**
- 12. Execute “FLASH.bat” file.**
- 13. Process to flash BIOS (don’t reset).**
- 14. After finish , Press the power button to shut down the system.**
- 15. Boot system , When you see the LOGO or hear one short beep, please press “Delete” to enter BIOS Setup Menu.**
- 16. Select “Load Default Settings” and press “Enter”.**
- 17. Select “Yes” to load default setting.**
- 18. Select “Save & Exit Setup” and press “Enter”.**
- 19. Select “Yes” to restart.**